

Trouble Shooting

Volume Larger Than Expected Con't

Adjustment of Acquisition PCB.

Note: Each time you make any adjustments on the Body Box Flow settings, you MUST Zero the DAC (As shown in Fig 1.) And carry out a reset, & Calibration.

The aim of adjusting Pot 37 is to tune the flow calibrations, so when performing the strokes, they end in the same place, And don't drift along the baseline. (As shown in Fig 2.)

